MAR 22 1988

Mr. Richard J. Schmitz Environmental Engineer, LILCO 1660 Walt Whitman Road Melville, New York 11747

CERTIFIED MAIL #338 228 231 RETURN RECEIPT REQUESTED

Dear Mr. Schmitz:

On February 17, 1988, Mr. James Manfreda, Roy F. Weston Co., contractor to the U.S. EPA, and myself visited the West Babylon and E. F. Barrett facilities to inspect the recently installed tank truck unloading catchment system and impermeable liners of the #2 fuel oil and waste oil tank dike floors.

The fuel oil loading containment areas at the West Babylon and Barrett facilities appear adequate to contain a spill from tank truck unloading at these facilities.

The installation of the environat containment system for the #2 fuel oil and waste oil tanks at the West Babylon and Barrett facilities appear adequate to contain a spill in these areas.

The SPCC plans for these facilities must be amended to reflect these changes before compliance can be considered.

At your convenience, we plan to visit the other LILCO facilities in mid-March.

Thank you for your cooperation.

Sincerely yours,

Charles Fitzsimmons Response and Prevention Branch, U.S. EPA

◆U.S. GPO : 1986-159-319

CONCURRENCES							
SYMBOL	File: 1.	TAT (Da	a Entry) 2.	Harris 3.	EPA File		•
SURNAME	2ERR-RP		ZERR-RP:TAT	8:g1:03/03/88 2ERR-RP	2ERR-RP	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •
DATE	MANFREDA	u	HENNE 3/3/4	FLTZSIMMONS			• • • • • • • • • • • • • • • • • • • •
EPA Form	1320-4 (12-70)			07 5-7-88	2-7-88	OFFICIA	L FILE COPY